

ACCIDENT CLASSIFICATION

UNIT **7 E.F.T.S Windsor**

COM. **1**

PLACE **M.A.**

DATE **19-9-43** TIME **1455**

H.Q. FILE **1100-12-72**

A/C TYPE **TIGER MOTH 82C**

No. **1272**

CRASH CAT. **"B"**

S.E. **x**

M.E.

DAY **x**

NIGHT

COMMAND

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

Kent, A.H.

LAC

R217316

PP

Uninj.

No. **E.34**

DATE **20-9**

D 14 (REVISED)

No. **2**

CHECKED

#37

MONTH

FORCED LANDING

TAXYING

LANDING

TAKE-OFF

FLIGHT

STATUARY

FATAL

INJ

3RD

5

STAGE OF FLIGHT

ENGINE

ENGINE NUMBER (S)

HOURS FLOWN BY PILOTS

Gipsy Major IC 7817/85681

seriously

INST.

NIGHT

ON TYPE

TOTAL

SOLO

DUAL

SOLO

DUAL

-

-

-

1000

-

1000

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

First solo.

TECHNICAL OFFICER'S REPORT:

Nil *LS/*

NATURE OF ACCIDENT:

Bounced on landing. Applied wrong rudder. A/C swung off runway at 90° angle. Struck rough ground before becoming airborne and overturned.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~40. Heavy landing - flying into ground.~~ (4)

SECONDARY OR CONTRIBUTORY FACTORS:

~~14. Misuse of controls.~~

ACTION TAKEN:

~~37. Overturning.~~

Log book endorsed.