

CASPIR Aircraft Accident Cards

Serial: AS738

Title: Airspeed Oxford Mk. II serial:AS738 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-September-01. Oxford II s/n AS738. This accident involved 1 person. Uppard H

Keywords: RAFOxford II,AS738,35 SFTS,35 Service Flying Training School,Aerodrome,1943-September-01,UppardRCAF L20

Created: 1943-09-01

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS738>

ACCIDENT CLASSIFICATION


UNIT 35 S.F.T.S North Battleford		COM. 4	PLACE M.A.		DATE 1-9-43	TIME 1250		
A/C TYPE OXFORD II		NO. AS738		CRASH CAT. "C"3	H.Q. FILE 1300-AS738			
PERSONNEL Uppard, H.		RANK Cpl	NUMBER 551631	DUTY PP	INJURIES Uninj.		SIGNAL NO. DATE A.1056 1-9	
							D 14 (REVISED)	
							NO. CHECKED 1 <input checked="" type="checkbox"/>	
							#1	
ENGINE Cheetah X	ENGINE NUMBER (S) 227439/4844266 Nil 227322/AS44149 11		HOURS FLOWN BY PILOTS				STAGE OF FLIGHT	
			INST.	NIGHT	ON TYPE		TOTAL	
					SOLO	DUAL	SOLO DUAL	
			11	3	8	18	37 65	

TYPE OF A/C
TYPE OF UNIT
CATEGORY

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE OFF
FLIGHT
STAT RV
FATAL
INJ.
3RD
INJURY

ACCIDENT CLASSIFICATION



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Flying training.

Nil

12/14/53/1055/w/w/c

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

Landed a/c with drift due to cross-wind. Stbd. u/c collapsed and a/c groundlooped.

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~61. Swinging on landing.~~

2. Swinging

2

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil