

## CASPIR Aircraft Accident Cards

---

**Serial:** AT525

**Title:** Airspeed Oxford Mk. I serial:AT525 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-September-21. Oxford II s/n AT525. This accident involved 2 people. Green AA, Pitt JD

**Keywords:** RAFOxford II,AT525,35 SFTS,35 Service Flying Training School,Aerodrome,1943-September-21,Green,PittRCAF L20

**Created:** 1943-09-21

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AT525>



PURPOSE OF FLIGHT:

Flying training.

TECHNICAL OFFICER'S REPORT:

Nil

*000/01B*

NATURE OF ACCIDENT:

Tire burst on take-off. A/c swing off runway and nosed.up.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~15. Tire failure.~~

14. Out of control

14

SECONDARY OR CONTRIBUTORY FACTORS:

~~9. Swinging.~~

~~36. Nosing up.~~

37. Tire Burst

37

ACTION TAKEN:

Nil