

## CASPIR Aircraft Accident Cards

---

**Serial:** FE281

**Title:** North American Harvard Mk. IIB serial:FE281 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-October-01. Harvard II s/n FE281. This accident involved 1 person. Hoare HF

**Keywords:** RAFHarvard II,FE281,41 SFTS,41 Service Flying Training School,Aerodrome,1943-October-01,HoareRCAF L20

**Created:** 1943-10-01

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE281>



PURPOSE OF FLIGHT:

Exercises 6.7.8.

TECHNICAL OFFICER'S REPORT:

No Technical defects.

NATURE OF ACCIDENT:

Pupil on first solo made  
landing with slight drift. On  
touching down aircraft swung violently  
and ground looped.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LS/PSHP/WWC

CLASSIFICATION:

35. Cross winds and gusts. (2)

SECONDARY OR CONTRIBUTORY FACTORS:

38. Ground loop  
25. Inexperience.

ACTION TAKEN:

Nil.