

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ737

**Title:** North American Harvard Mk. II serial:AJ737 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-October-02. Harvard II s/n AJ737. This accident involved 2 people. Sarginson J, Mclaughlan PS

**Keywords:** RAFHarvard II,AJ737,34 SFTS,34 Service Flying Training School,Aerodrome,1943-October-02,Mclaughlan,SarginsonRCAF L20

**Created:** 1943-10-02

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ737>

62 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31 7 4 2 1

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 2-10-43		TIME 1830			
			H.Q. FILE 1300-AJ737					
A/C TYPE HARVARD II	No. AJ737	CRASH CAT. "D"1/32	S.E. x	M.E.	DAY x	NIGHT		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
Sarginson, J.		SGT	1600147	FI	Unknj.		No.	DATE
McLaughlan, P.S.		LAC	1671983	PP	Uninj.			
<p style="text-align: center; font-size: 2em; opacity: 0.5;">New York</p>							D 14 (REVISED)	
							No. 6	CHECKED X
							#21	
ENGINE Wasp S3HI	ENGINE NUMBER (S) 10986/A213612 Nil		HOURS FLOWN BY PILOTS				STAGE OF FLIGHT	
			INST.	NIGHT	ON TYPE		TOTAL	
			-	-	SOLO	DUAL	SOLO	DUAL
					250	120	300	200

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
 TAXING  
 LANDING  
 TAKEOFF  
 FLIGHT  
 STATRY  
 FATAL  
 INJURY  
 3RD  
 5

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Dual instruction.

Stbd wheel tire burst after life of 21.30 hours.

NATURE OF ACCIDENT:

Stbd tire punctured by piece of wire while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Tire B

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

(Nil)