

CASPIR Aircraft Accident Cards

Serial: AJ728

Title: North American Harvard Mk. II serial:AJ728 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-October-11. Harvard II s/n AJ728. This accident involved 2 people. Murcek V, Kovac V

Keywords: RAFHarvard II,AJ728,34 SFTS,34 Service Flying Training School,Aerodrome,1943-October-11,Kovac,MurcekRCAF L20

Created: 1943-10-11

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ728>

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 11-10-43		TIME 1140			
			H.Q. FILE 1300-AJ728					
A/C TYPE HARVARD II	No. AJ728	CRASH CAT. "D"1/72	S.E. X	M.E.	DAY X	NIGHT		
PERSONNEL	RANK	NUMBER	DUTY	INJURIES		SIGNAL		
Murcek, V.	F/O	118597	FI	Uninj.		NO. DATE		
Kovac, V.	F/S	787274	PP	Uninj.		D 14 (REVISED)		
<p style="font-size: 2em; opacity: 0.5;">TANK FAILURE</p>						NO. CHECKED		
						26	X	
						#71		
ENGINE	ENGINE NUMBER(S)		HOURS FLOWN BY PILOTS					
Wasp S3HI	4282/8423 Nil		INST.	NIGHT	ON TYPE		TOTAL	
			-	-	SOLO	DUAL	SOLO	DUAL
					450	-	5800	-

TYPE OF A/C
TYPE OF UNIT
CATEGORY

COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

Flapless landings.

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 39 hours.

NATURE OF ACCIDENT:

Tail wheel tire burst during landing run.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

W

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil