

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 11-10-43	TIME 1140
A/C TYPE HARVARD II		No. AJ728	CRASH CAT. "D"1/72	H.Q. FILE 1300-AJ728
		S.E. X	M.E.	DAY X
				NIGHT

COMMAND

4
2
1
7
4
2
1

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL		
Murcek, V.	F/O	118597	FI	Uninj.	NO.	DATE	
Kovac, V.	F/S	787274	PP	Uninj.	D 14 (REVISED)		
<p>TAIL FAILURE</p>					NO.	CHECKED	
					26		X
					#71		

MONTH

1

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE OFF
FLIGHT
STATRY
FATAL
INJ.
INJURY

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS	ON TYPE				TOTAL	
			INST.	NIGHT	SOLO	DUAL	SOLO	DUAL
Wasp S3HI	4282/8423	Nil	-	-	450	-	5800	-

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62

3
2
1
4
3
2
1
5
4
3
2
1
M
N

PURPOSE OF FLIGHT:

Flapless landings.

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 39 hours.

NATURE OF ACCIDENT:

Tail wheel tire burst during landing run.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

W

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil