

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 17-10-48	TIME 1745				
	H.Q. FILE 1300-AJ729							
A/C TYPE HARVARD II	NO. AJ729	CRASH CAT. "D"1/72	S.E. x	M.E.	DAY x	NIGHT		
PERSONNEL Tonge, P.	RANK LAC	NUMBER 1684770	DUTY PP	INJURIES Uninj.		SIGNAL NO. DATE		
<p style="font-size: 2em; font-weight: bold;">TIRE FAILURE</p>						D 14 (REVISED)		
						NO. 38	CHECKED <input checked="" type="checkbox"/>	
						#103		
ENGINE Wasp S3HI	ENGINE NUMBER (S) A213610/10984	NI1	HOURS FLOWN BY PILOTS					
			INST.	NIGHT	ON TYPE		TOTAL	
			SOLO	DUAL	SOLO	DUAL		
			-	-	1	8	37	41

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE OFF
FLIGHT
STAT RV
FATAL
INJ.
INJURY

RAF M N

PURPOSE OF FLIGHT:

Solo circuits and landings.

TECHNICAL OFFICER'S REPORT:

Port main tire burst, on landing after life of 67 hours

NATURE OF ACCIDENT:

Port tire burst on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

15/10

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil