



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Taxiing a/c from hangar to taxi strip.

Nil

NATURE OF ACCIDENT:

Taxiing a/c from hangar to taxi strip on approaching gun mounting at the stop butts applied left brake and rudder, but a/c failed to swing, striking gun mounting with stbd wing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TCC/PST ✓

CLASSIFICATION:

~~2. Hitting obstructions.~~ 9

*Collisions*

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Log book endorsed "Carelessness" Recommendation being sent to #4 T.C. to have gun mounting in question removed.