

CASPIR Aircraft Accident Cards

Serial: 2792

Title: North American Harvard Mk.II serial:2792 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-October-19. Harvard II s/n 2792. This accident involved 2 people. Teesdale JAM, Foot EJ

Keywords: RAFHarvard II,2792,34 SFTS,34 Service Flying Training School,Aerodrome,1943-October-19,Foot,TeesdaleRCAF L20

Created: 1943-10-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2792>

PURPOSE OF FLIGHT:

N/F circuits and landings.

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 11430 hours.

NATURE OF ACCIDENT:

Tail wheel tire burst while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil