

CASPIR Aircraft Accident Cards

Serial: FE285

Title: North American Harvard Mk. IIB serial:FE285 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-October-20. Harvard IIB s/n FE285. This accident involved 2 people. Bligh GR, Meadows GA

Keywords: RAFHarvard IIB,FE285,34 SFTS,34 Service Flying Training School,Aerodrome,1943-October-20,Bligh,MeadowsRCAF L20

Created: 1943-10-20

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE285>

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 20-10-43	TIME 1715
A/C TYPE HARVARD IIB		NO. FE285	CRASH CAT. "D"1/72	H.Q. FILE 1300-FE285
		S.E. X	M.E.	DAY X
				NIGHT

COMMAND

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Bligh, G.R.	SGT	1445545	FI	Uninj.	NO.	DATE
Meadows, G.A.	LAC	1567637	PP	Uninj.		

MONTH

TIME FAILURE

D 14 (REVISED)	
NO.	CHECKED
49	<input checked="" type="checkbox"/>
#118	

STAGE OF FLIGHT

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS					
Wasp R1340 AM I	41-12433/1391C Nil	INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		-	-	700	70	760	118

FORCED LANDING

TAXIING

LANDING

TAKE-OFF

FLIGHT

STATRY

FATAL

INJ

3RD

INJURY

RAF

M

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Dual exercises.

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 111.40 hours.

NATURE OF ACCIDENT:

Tail wheel tire burst while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil