

CASPIR Aircraft Accident Cards

Serial: FE919

Title: North American Harvard Mk. IIB serial:FE919 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-October-25. Harvard IIB s/n FE919. This accident involved 2 people. Jackson LJ, Coll AE

Keywords: RAFHarvard IIB,FE919,34 SFTS,34 Service Flying Training School,Aerodrome,1943-October-25,Coll,JacksonRCAF L20

Created: 1943-10-25

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE919>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Dual exercise.

Tail wheel tire burst after life of 8.30 hours.

NATURE OF ACCIDENT:

Tail wheel tire burst while taxiing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

7:30 /

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil