

62
61
60
59
58
57
56
55
54
53
52
51
50
49
48
47
46
45
44
43
42
41
40
39
38
37
36
35
34
33
32
31

ACCIDENT CLASSIFICATION

UNIT 3 S.F.T.S. Calgary	COM. 4	PLACE MA.	DATE 26-10-43 TIME 0200						
	A/C TYPE CRANE I CRANE I		No. 8682 8178	CRASH CAT. "C" "D"2½	H.Q. FILE 1100-86-82				
PERSONNEL Nicholls, W.H.		RANK SGT	NUMBER R225304	DUTY PP	INJURIES Uninj.				
ENGINE Jacobs L4MB		ENGINE NUMBER (S) 21530/4400 Nil 21167/4023 Nil 21998/4747 Nil 22061/8143 Nil		HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL			
				SOLO	DUAL	SOLO	DUAL		
				18	18	35	43	75	79

COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
3RD
INJURY
5
4

ACCIDENT CLASSIFICATION

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62

PURPOSE OF FLIGHT:

Solo night circuits.

TECHNICAL OFFICER'S REPORT:

Nil

Muz
TCN/PC
M/1/84

NATURE OF ACCIDENT:

Pilot in a/c 8682 while attempting to park a/c on tarmac after a night exercise. taxied into a/c 8178. A/C pilot struck had its lights out as the battery had gone dead while parked on Tarmac.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Pilot did not wait for signal to taxi into the line and as all ground crew were busy at time there was no one on hand to guide him.

CLASSIFICATION:

~~3. Hitting other a/c.~~

Collisions.

①

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed for Negligence and reprimanded.