

CASPIR Aircraft Accident Cards

Serial: EB509

Title: Airspeed Oxford Mk. V serial:EB509 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-October-07. Oxford V s/n EB509. This accident involved 2 people. MacArthur HN, Beal DC

Keywords: RAFOxford V,EB509,35 SFTS,35 Service Flying Training School,R1 Hamlin,1943-October-07,Beal,MacArthurRCAF L20

Created: 1943-10-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#EB509>

ACCIDENT CLASSIFICATION

UNIT 35 S.F.T.S.		COM. 4	PLACE RI Hamlin		DATE 7-10-43	TIME 0830			
North Battleford					H.Q. FILE 1300-EE709				
A/C TYPE OXFORD V		No. EB509	CRASH CAT. "C"2		S.E. x	M.E. x	DAY x	NIGHT	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL		
MacArthur, H.N.		P/O	152027	FI	Uninj.		NO.	DATE	
Beal, J.C.		LAC	167557	PP	Uninj.		A.124	7-10	
							D 14 (REVISED)		
							NO. 6	CHECKED <input checked="" type="checkbox"/>	
							#8		
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				STAGE OF FLIGHT	
Wasp Junior	5147/1851	Nil		INST.	NIGHT	ON TYPE		TOTAL	
	5157/18861	Nil				SOLO	DUAL	SOLO	DUAL
				41	53	214	9	349	159
				8	6	-	3	29	47

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

- () FORCES LANDING
- () TAXIING
- () LANDING
- () TAKE OFF
- () FLIGHT
- () STAIRY
- () FATAL
- () INJ. 1st
- () INJ. 2nd
- () INJ. 3rd
- () INJ. 4th
- () INJ. 5th
- () INJ. 6th

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Flying training.

Nil

12/11/50 down 2/10/51

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

Pupil completed landing. Instructor took over and as he was taxiing a/c horn commenced to blow and, in spite of his efforts in using hand pump, u/c collapsed.

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~31. U/C down but not fully locked.~~

8

U/C. FAILURE

SECONDARY OR CONTRIBUTORY FACTORS:

U/C. DRILL-ON-GROUND

33

ACTION TAKEN:

Nil