

CASPIR Aircraft Accident Cards

Serial: AS850

Title: Airspeed Oxford Mk. II serial:AS850 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-October-07. Oxford II s/n AS850. This accident involved 1 person. Mackay A

Keywords: RAFOxford II,AS850,35 SFTS,35 Service Flying Training School,R1 Hamlin,1943-October-07,MackayRCAF L20

Created: 1943-10-07

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS850>

62 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 35 S.F.T.S. Battleford	COM. 4	PLACE RI Hamlin	DATE 7-10-43	TIME 2145				
	A/C TYPE OXFORD II	No. AS850	CRASH CAT. "C"4	H.Q. FILE 1300-AS850				
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
Mac Kay, A.		LAC	1672817	PP	Uninj.		NO. A.131	DATE 8-10
							D 14 (REVISED)	
							NO. 7	CHECKED X
							#10	
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Cheetah X	227553/AS44380		INST.	NIGHT	ON TYPE		TOTAL	
	227538/AS44365				SOLO	DUAL	SOLO	DUAL
			19	18	37	44	72	96

COMMAND
MONTH
STAGE OF FLIGHT

Forced Landing
TAXIING
LANDING
TAKEOFF
FLIGHT
STATRY
FATAL
INJURY
3rd
5

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M N

PURPOSE OF FLIGHT:

Night flying training.

TECHNICAL OFFICER'S REPORT:

Nil

10/1/50

NATURE OF ACCIDENT:

Making night landing touched down too fast and overshot runway, running into ditch.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~29. Overshooting runway,~~
OVERSHOT.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Log book endorsed.