

ACCIDENT CLASSIFICATION														
UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.			DATE 1-11-43	TIME 2115								
	A/C TYPE HARVARD II			NO. AJ791	CRASH CAT. "B"	S.E. X	M.E.	DAY	NIGHT X					
PERSONNEL Ekinsmyth, E.B.		RANK F/O	NUMBER 407042	DUTY P	INJURIES Uninj.		SIGNAL No. DATE A.882 2-11							
							D 14 (REVISED) No. CHECKED 3 <input checked="" type="checkbox"/>							
							#8							
ENGINE Wasp S3HI		ENGINE NUMBER (S) a62247/12177 slight.		HOURS FLOWN BY PILOTS										
				INST.	NIGHT	ON TYPE		TOTAL						
						SOLO	DUAL	SOLO	DUAL					
				24	16	20	22	67	89					
ACCIDENT CLASSIFICATION														

TYPE OF A/C  
TYPE OF UNIT  
CATEGORY

COMMAND  
MONTH  
STAGE OF FLIGHT

7  
2  
1  
7  
4  
2  
1  
1  
FORCED LANDING  
TAXIING  
LANDING  
TAKEOFF  
FLIGHT  
STATRY  
FATAL  
INJ.  
3RD  
INJURY  
5  
RAF  
M X

PURPOSE OF FLIGHT:

Night flying circuits.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pupil attempting to do overshoot at night struck the side of a hill slope at leeward end of aerodrome.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LO/P30 ✓

CLASSIFICATION:

~~29. Overshooting runway.~~

1. Overshot

SECONDARY OR CONTRIBUTORY FACTORS:

~~11. Hitting obstructions.~~

ACTION TAKEN:

Nil