

CASPIR Aircraft Accident Cards

Serial: AJ921

Title: North American Harvard Mk. II serial:AJ921 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-02. Harvard II s/n AJ921. This accident involved 1 person. Wijting

Keywords: RAFHarvard II,AJ921,34 SFTS,34 Service Flying Training School,Aerodrome,1943-November-02,WijtingRCAF L20

Created: 1943-11-02

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ921>

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32

ACCIDENT CLASSIFICATION

UNIT No. 34 S.F.T.S. Medicine Hat.	COM. # 4	PLACE M.A.	DATE 2-11-43	TIME 1210				
	H.Q. FILE							
A/C TYPE Harvard II	No. AJ921	CRASH CAT. D 1/32	S.E. x	M.E.	DAY x	NIGHT		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
Wijting,		LAC	1814907	PP	Nil		No.	DATE
							D 14 (REVISED)	
							No. 4	CHECKED X
							No. 29	
ENGINE	ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Wasp S3H1	213324/9960 Nil		INST.	NIGHT	ON TYPE		TOTAL	
			-	-	SOLO	DUAL	SOLO	DUAL
					8	17	44	62

CATEGORY
TYPE OF UNIT
TYPE OF A/C
COMMAND
MONTH
STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
INJURY
3RD
5
RAF

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

PURPOSE OF FLIGHT:

Circuits and landings.

TECHNICAL OFFICER'S REPORT:

Port tyre burst after life of 354:05 hours.

NATURE OF ACCIDENT:

Port tyre burst on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL