

## CASPIR Aircraft Accident Cards

---

**Serial:** 2552

**Title:** North American Harvard Mk.II serial:2552 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-November-02. Harvard II s/n 2552. This accident involved 1 person. Parsons WJ

**Keywords:** RAFHarvard II,2552,41 SFTS,41 Service Flying Training School,Stoughton Saskatchewan,1943-November-02,ParsonsRCAF L20

**Created:** 1943-11-02

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2552>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Forced landing practice.

Nil

*FB/ASST/PCDE/ST/PM/PH/E/OK/B*

NATURE OF ACCIDENT:

forced

Pupil carrying out authorized, landing practice allowed his engine to get cold and was without power when he attempted to climb.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~24. Carelessness.~~

*17 Forced Landing*

*30321*

SECONDARY OR CONTRIBUTORY FACTORS:

~~54. Engine failure in the air.~~

~~34. Wheels up landing.~~

ACTION TAKEN:

Log book endorsed "Carelessness".

*No. Engine Trouble - 26 Accident*

R. C. A. F. L 20 (REVISED)  
7M-4-43 (3262) K. P. 5051  
H. G. 885-L 20