

61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 37 S.F.T.S. Calgary	COM. 4	PLACE M. A.	DATE 5-11-43	TIME 0105			
A/C TYPE HARVARD II HARVARD II		NO. AJ794 D AJ910	CRASH CAT. "C"2 "D"1	H.Q. FILE 1300-AJ794			
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Beeton, A.B.		GB LAC	1583086	FP	Uninj.	NO.	DATE
LeVerteuil, D.C.		F/O	153669	FI	Uninj.	A.165	5-11
						D 14 (REVISED)	
						NO.	CHECKED
						2	X
						#18	

COMMAND

MONTH

STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJURY
3rd
5

TYPE OF A/C
TYPE OF UNIT
CATEGORY

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M 4

ACCIDENT CLASSIFICATION

ENGINE Wasp 33HI	ENGINE NUMBER (S) 13089/202254 Nil 11574/213845 Nil	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
		12 69	4 79	12 687	34 84	48 789	85 161

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Taxiing a/c Harvard AJ794 to hangar.

Nil

NATURE OF ACCIDENT:

Pupil pilot of a/c HARVARD AJ794 taxiing a/c to hangar collided with a/c AJ910.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

MULT

SUMMARY No.

TCA/ACT

TCA/VA

CLASSIFICATION:

~~3. Hitting other a/c.~~

9

9. Collision

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil