

CASPIR Aircraft Accident Cards

Serial: 2613

Title: North American Harvard Mk.II serial:2613 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-06. Harvard II s/n 2613. This accident involved 2 people. Sharpe RD, Crawford JL

Keywords: RAFHarvard II,2613,34 SFTS,34 Service Flying Training School,Holsom R1,1943-November-06,Crawford,SharpeRCAF L20

Created: 1943-11-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2613>

PURPOSE OF FLIGHT:

Circuits and landings.

TECHNICAL OFFICER'S REPORT:

Burst tail wheel tire after life of 83.15 hours.

NATURE OF ACCIDENT:

Burst tailwheel tire while taxiing off landing path.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TU/UT-1

CLASSIFICATION:

43. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil