

102 61 60 59 58 57 56 55 54 53 52 51 50 49 48 47 46 45 44 43 42 41 40 39 38 37 36 35 34 33 32 31

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat.	COM. 4	PLACE M.A.	DATE 12-11-48	TIME 0800
A/C TYPE NAV VAPOR II		No. 2736	CRASH CAT. "D" 2	H.Q. FILE 1190-27-35
		S.E. X	M.E. X	DAY X
				NIGHT

COMMAND

PERSONNEL Sheppard R.A.	RANK Cpl.	NUMBER 610882	DUTY PP	INJURIES Uninj.	SIGNAL No. A930 DATE 13-11
----------------------------	--------------	------------------	------------	--------------------	----------------------------------

MONTH

D 14 (REVISED)	
No. 20	CHECKED <input checked="" type="checkbox"/>
#48	

STAGE OF FLIGHT

ENGINE Wasp 33H1	ENGINE NUMBER (S) 13145/262310	Nil	HOURS FLOWN BY PILOTS				
		INST.	NIGHT	ON TYPE		TOTAL	
		-	-	SOLO	DUAL	SOLO	DUAL
				25	48	65	95

FORCED LANDING
TAXIING
LANDING
TAKEOFF
FLIGHT
STATIONARY
FATAL
INJURY
3RD
5

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF MZ

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Forced landing ap roaches.

Nil

NATURE OF ACCIDENT:

Ground looped after landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LS/PSS ✓

CLASSIFICATION:

~~38~~ Ground loop.

2 Swing 2

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil