



PURPOSE OF FLIGHT:

Circuits and landings.

NATURE OF ACCIDENT:

Tail wheel tire burst while taxiing.

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 104.5 hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TU: /

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil