

CASPIR Aircraft Accident Cards

Serial: FE912

Title: North American Harvard Mk. IIB serial:FE912 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-15. Harvard IIB s/n FE912. This accident involved 2 people. Bond DL, Burberry UL

Keywords: RAFHarvard IIB,FE912,34 SFTS,34 Service Flying Training School,Aerodrome,1943-November-15,Bond,BurberryRCAF L20

Created: 1943-11-15

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE912>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

I.F. Take-offs.

Nil

NATURE OF ACCIDENT:

Ground loop on landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LS/PSS/I ✓

CLASSIFICATION:

~~38. Ground loop.~~

2

2. Swing

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil