

CASPIR Aircraft Accident Cards

Serial: FE280

Title: North American Harvard Mk. IIB serial:FE280 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-19. Harvard II s/n FE280. This accident involved 1 person. Jones JE

Keywords: RAFHarvard II,FE280,41 SFTS,41 Service Flying Training School,Aerodrome,1943-November-19,JonesRCAF L20

Created: 1943-11-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE280>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Precautionary landing practice.

Nil

NATURE OF ACCIDENT:

On approach pilot opened throttle at 300' but engine did not pick up immediately. A/C bounded, stbd wing dropped and struck ground.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LH/25117

CLASSIFICATION:

~~58. Precautionary landings.~~

4. Heavy

4

SECONDARY OR CONTRIBUTORY FACTORS:

~~40. Heavy landing - flying into ground.~~

32. Pilot error.

ACTION TAKEN:

Nil