

CASPIR Aircraft Accident Cards

Serial: FE348

Title: North American Harvard Mk. IIB serial:FE348 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-22. Harvard II s/n FE348. This accident involved 1 person. Bouche JJ

Keywords: RAFHarvard II,FE348,41 SFTS,41 Service Flying Training School,Aerodrome,1943-November-22,BoucheRCAF L20

Created: 1943-11-22

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE348>

PURPOSE OF FLIGHT:

Solo Cross Country.

TECHNICAL OFFICER'S REPORT:

NIL.

NATURE OF ACCIDENT:

After landing the aircraft developed a swing. Pilot was unable to correct and a ground loop resulted.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

LS/PSS ✓

CLASSIFICATION:

~~61. Swinging on landing.~~

2. Swing 2

SECONDARY OR CONTRIBUTORY FACTORS:

~~38. Ground loop.~~

ACTION TAKEN:

NIL.