

CASPIR Aircraft Accident Cards

Serial: 2986

Title: North American Harvard Mk.II serial:2986 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-November-27. Harvard II s/n 2986. This accident involved 1 person. De Groeve IP

Keywords: RAFHarvard II,2986,34 SFTS,34 Service Flying Training School,Aerodrome,1943-November-27,De GroeveRCAF L20

Created: 1943-11-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2986>

PURPOSE OF FLIGHT:

N/F Circuits & Landings

TECHNICAL OFFICER'S REPORT:

Port wheel tyre burst after life of 154.00 hours.

NATURE OF ACCIDENT:

Port tyre burst on landing at night.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

20/07/11

CLASSIFICATION:

43. Tire trouble

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.