

## CASPIR Aircraft Accident Cards

---

**Serial:** 2564

**Title:** North American Harvard Mk.II serial:2564 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-November-30. Harvard II s/n 2564. This accident involved 2 people. Cadden J, Davis R

**Keywords:** RAFHarvard II,2564,34 SFTS,34 Service Flying Training School,Aerodrome,1943-November-30,Cadden,DavisRCAF L20

**Created:** 1943-11-30

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2564>



PURPOSE OF FLIGHT:

Check circuits.

NATURE OF ACCIDENT:

Stbd. tyre burst after landing.

TECHNICAL OFFICER'S REPORT:

Stbd. wheel tyre burst after life of 260.50 Hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

*10/10/53*

CLASSIFICATION:

43. Tire trouble

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.