



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Mutual instruction.

Piston material and bearing metal found in cylinder 2, 4, 5, and 6. Suspected partial piston and piston ring failure since compression was low on four cylinders

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

P/O Allaster, with P/O Axford as passenger, was carrying out authorized low flying in low flying area, the engine failed at 800' and a successful forced landing was carried out.

FINDINGS:

SUMMARY No.

IL - ~~PA~~ AOP/E S/IM/D/IL

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil