

ACCIDENT CLASSIFICATION

UNIT 1 O.T.U. Ba. otville, Ont.		COM. E	PLACE Mid air between Bagotville and Chicoutime		DATE 20-11-43	TIME 1820 GMT	
A/C TYPE HURRICANE XIIA HURRICANE XIIA		No. BWC35 BW859	CRASH CAT. "D"2 "B"	S.E. X	M.E.	DAY X	NIGHT
H.Q. FILE 1300-BW835		PERSONNEL		RANK	NUMBER	DUTY	INJURIES
Wadsworth, R.S.		F/L	66524	P		Uninj.	
Mace, W.W.-		AUSEGT	14809	P		Uninj.	
SIGNAL		NO.	DATE		D 14 (REVISED)		
A.525		21-11	NO.		CHECKED		
#7		6	✓				
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS			
Packard Merlin		A285/A301 Nil		ON TYPE		TOTAL	
				INST.	NIGHT	SOLO	DUAL
				63	140	28	-
				58	81	10	-
						1700	77
						765	160

COMMAND  
MONTH  
STAGE OF FLIGHT

FORCED LANDING  
TAXIING  
LANDING  
TAKE-OFF  
FLIGHT  
START BY  
FATAL  
INJ.  
3rd  
INJ.

ACCIDENT CLASSIFICATION

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 RAF M

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Formation flying.

Nil

*12/11*  
*12/11*  
*12/11*

NATURE OF ACCIDENT:

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

When doing a cross overturn pilot of Hurricane BW835 collided with Hurricane BW859 damaging wing of Hurricane BW835 and fuselage and tail assembly of Hurricane BW859. Both a/c returned to base and landed safely.

FINDINGS:

SUMMARY No.

CLASSIFICATION:

- 26. ~~Collision in the air.~~ *21*
- 21. *Collision - a/c*

SECONDARY OR CONTRIBUTORY FACTORS:

~~24 Carelessness.~~

ACTION TAKEN:

Log book endorsed and pilot of Hurricane BW835 re-tarded on course.