

ACCIDENT CLASSIFICATION

UNIT 35 E.F.T.S. NEEPAWA, Manitoba.	COM. 2	PLACE 4 miles due East of NEEPAWA Aerodrome	DATE 8-11-43	TIME 17:00
A/C TYPE TIGER MOT, D.H. 82 c.		No. 4989	CRASH CAT. FLD	H.Q. FILE 1100-49-89
S.E. X	M.E.	DAY X	NIGHT	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
GARNETT, J.D.	F/S	655509	FI	Uninj.	No.	DATE
YAXLEY, G..	LAC	1621928	PP	Uninj.	D 14 (REVISED)	
					No.	CHECKED
					1	#18

ENGINE	ENGINE NUMBER(S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
GYPSY MAJOR	89153/7331						
		47	154	1600	67	1640	92
		2	-	10	12	11	12

ACCIDENT CLASSIFICATION

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXIING

LANDING

TAKEOFF

FLIGHT

STATRY

FATAL

INJURY

Grid of circles for classification, numbered 1 to 31 on the top and bottom edges, and 1 to 7 on the right edge.

PURPOSE OF FLIGHT:

Exercise No. 18 Dual Instruction on I.F.

TECHNICAL OFFICER'S REPORT:

No. 4 Cylinder Head, Cylinder Barrel and Piston damaged.

NATURE OF ACCIDENT:

During Dual Instruction on Instrument Flying, the engine cut out completely, without warning, and a forced landing was necessitated.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

PB/AOF/FS/MP/D/E

CLASSIFICATION:

54 Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil