

CASPIR Aircraft Accident Cards

Serial: 2792

Title: North American Harvard Mk.II serial:2792 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1943-December-03. Harvard II s/n 2792. This accident involved 2 people. Whiteside L, Williams GA

Keywords: RAFHarvard II,2792,34 SFTS,34 Service Flying Training School,Aerodrome,1943-December-03,Whiteside,WilliamsRCAF L20

Created: 1943-12-03

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2792>

81 () 60 () 59 () 58 () 57 () 56 () 55 () 54 () 53 () 52 () 51 () 50 () 49 () 48 () 47 () 46 () 45 () 44 () 43 () 42 () 41 () 40 () 39 () 38 () 37 () 36 () 35 () 34 () 33 () 32 () 31 ()

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine hat.	COM. 4	PLACE L.A.	DATE 3-12-43	TIME 1445
A/C TYPE HARVARD II		NO. 2792	CRASH CAT. "E"	H.Q. FILE 1100-27-2
		S.E. x	M.E.	DAY x
				NIGHT

TYPE OF A/C

TYPE OF UNIT

CATEGORY

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Whiteside, L.	F/Lt.	63446	F.I.	Uninj.	NO.	DATE
Williams, G.A.	LAC	1677248	P.P.	Uninj.		
					D 14 (REVISED)	
					NO.	CHECKED
					12/7	
					#25	

COMMAND

MONTH

STAGE OF FLIGHT

7 ()
4 ()
2 ()
1 ()
7 ()
4 ()
2 ()
1 ()
FORCED LANDING ()
TAXIING ()
LANDING ()
TAKE-OFF ()
FLIGHT ()
STRATRY ()
FATAL ()
INJ. ()
3RD ()
5 ()
RAF ()
M ()

1 () 2 () 3 () 4 () 5 () 6 () 7 () 8 () 9 () 10 () 11 () 12 () 13 () 14 () 15 () 16 () 17 () 18 () 19 () 20 () 21 () 22 () 23 () 24 () 25 () 26 () 27 () 28 () 29 () 30 ()

ACCIDENT CLASSIFICATION

1 () 2 () 3 () 4 () 5 () 6 () 7 () 8 () 9 () 10 () 11 () 12 () 13 () 14 () 15 () 16 () 17 () 18 () 19 () 20 () 21 () 22 () 23 () 24 () 25 () 26 () 27 () 28 () 29 () 30 ()

PURPOSE OF FLIGHT:

"D" Test Practice.

NATURE OF ACCIDENT:

Burst tail wheel tyre.

TECHNICAL OFFICER'S REPORT:

Tail wheel tyre burst after life of 154.05 hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

43. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.