

## CASPIR Aircraft Accident Cards

---

**Serial:** 2789

**Title:** North American Harvard Mk.II serial:2789 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1943-December-11. Harvard II s/n 2789. This accident involved 1 person. Darlington RFM

**Keywords:** RAFHarvard II,2789,34 SFTS,34 Service Flying Training School,Aerodrome,1943-December-11,DarlingtonRCAF L20

**Created:** 1943-12-11

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2789>



) PURPOSE OF FLIGHT:

) First Solo Flight.

) NATURE OF ACCIDENT:

) Tail wheel tyre burst during landing  
) run.

) TECHNICAL OFFICER'S REPORT:

) Tailwheel tyre burst after life of 116.45 hours.

) COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

) FINDINGS:

) SUMMARY No.

) CLASSIFICATION:

) 43.Tire trouble

) SECONDARY OR CONTRIBUTORY FACTORS:

) ACTION TAKEN:

) NIL.