

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S.
Medicine Hat.

COM. 4

PLACE M.A.

DATE 18-12-43 TIME 0945

H.Q. FILE 1100-27-89

A/C TYPE HARVARD II

NO. 2789

CRASH CAT. "E"

S.E. X

M.E.

DAY X

NIGHT

PERSONNEL

RANK

NUMBER

DUTY

INJURIES

SIGNAL

Roberts, E.J.

F/O

50609

F.I.

Uninj.

NO.

DATE

Broadhurst, A.E.

LAC

1802698

P.P.

Uninj.

D 14 (REVISED)

NO.

CHECKED

12/35

#91

ENGINE

ENGINE NUMBER (S)

Wasp S3H.1. A213765/11494 NIL

HOURS FLOWN BY PILOTS

INST.

NIGHT

ON TYPE

TOTAL

SOLO

DUAL

SOLO

DUAL

-

-

900

90

1147

125

-

-

2

16

34

49

ACCIDENT CLASSIFICATION

COMMAND

MONTH


STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATARY
FATAL
INJ
3RD
S
RAF
M

TYPE OF A/C

TYPE OF UNIT

CATEGORY



PURPOSE OF FLIGHT:

Dual Circuits & Landings.

TECHNICAL OFFICER'S REPORT:

Tail wheel axle sheared.

NATURE OF ACCIDENT:

Tail wheel broke off after landing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

33. Technical defect.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

NIL.