

```
PURPOSE OF FLIGHT:
                                          TECHNICAL OFFICER'S REPORT:
     Solo sew. practice. 5,6,7,8,9,10,
     12,13,14. (6000) '. 17 (3660) ' 20,21,22.
 NATURE OF ACCIDENT:
     A/C crashed and was completely de-Court of inquiry or investigating officer's Report:
     molished. A/C took off in a/c
                                         FINDINGS:
                                                                      SUMMARY No. 161
    FS859 having been instructed to
    preactice various sequences including
    spinning and steep turning. It was the
) first flight of a, c for that day. A farmer
 walking on road some 13 miles from aerodrome
heard an a/c backfire and looking up, saw the
) a/c, apparently in normal flight at a low
altitude, go into a dive from which he failed
to recover.
                                           CONCLUSIONS OF AL.B.
 CLASSIFICATION:
                                            Accident due to engine failure (which in the sub-
                                            ject of further investigation) and subsequent loss
                                            of control by the pupil pilot.
 SECONDARY OR CONTRIBUTORY FACTORS:
                                        ACTION TAKEN:
 R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
    H. Q. 885-L 20
```