

CASPIR Aircraft Accident Cards

Serial: 8380

Title: Avro Anson Mk. II serial:8380 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-December-06. Anson II s/n 8380. This accident involved 2 people. Kitchen HA, Thomson JEJ

Keywords: RCAFAnson II,8380,19 SFTS,19 Service Flying Training School,R1
Ensign,1943-December-06,Kitchen,ThomsonRCAF L20

Created: 1943-12-06

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8380>

ACCIDENT CLASSIFICATION

UNIT 19 S.F.T.S. Vulcan	COM. 4	PLACE R1. Ensigne	DATE 6-12-43	TIME 1600
A/C TYPE ANSON II		NO. 8380	CRASH CAT. "E"	H.Q. FILE 1100-83-80
		S.E.	M.E.	DAY
			x	x
		NIGHT		

PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL	
Thomson, J.E.J.	F/O	J14712	FI	Uninj.	NO.	DATE
Kitchen, H.A.	LAC	R163466	PP	Uninj.		
					D 14 (REVISED)	
					NO.	CHECKED
					#29	

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE		TOTAL	
				SOLO	DUAL	SOLO	DUAL
J. cobs L6MB	14997/26511	-	-	958	11125	1027	161
	14995/26509	-	-	35	52	30	88

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STAIR
FATAL
INJ.
3rd
5
M 2
RAF

Grid of circles for classification, numbered 1-31 on the top and 1-31 on the bottom. The grid is partially filled with handwritten marks, including a large 'X' in the bottom right corner.

PURPOSE OF FLIGHT:

Practice single-engine landings.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Student was doing single-engine landing. Wheels were not checked down either by student or instructor, consequently a wheels up landing was made.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

34. Wheels up landing.

SECONDARY OR CONTRIBUTORY FACTORS:

24, Carelessness.

ACTION TAKEN:

Charge placed against pilot.