

ACCIDENT CLASSIFICATION

UNIT 34 O.T.U. Pennfield Ridge	COM. E	PLACE M.A.	DATE 17-12-43	TIME 1230 GMT
A/C TYPE VENTURA II VENTURA III	NO. AE925 FD637	CRASH CAT. "C"5 "C"4	H.Q. FILE 1300-AE925	S.E. M.E. DAY NIGHT x x


PERSONNEL	RANK	NUMBER	DUTY	INJURIES	SIGNAL
Henning, H.J.M.	P/O	J35647	pP	Uninj.	No. DATE
Peterkin, F.D.	SGT	R166338	NAV	Uninj.	A.446 17-12
Matthews, D.J.	SGT	R194764	WAG	Uninj.	D 14 (REVISED)
Swartz, N.	SGT	R203363	AG	Uninj.	No. CHECKED
					4
					#4

ENGINE	ENGINE NUMBER(S)	INST.	NIGHT	HOURS FLOWN BY PILOTS			
				ON TYPE		TOTAL	
P & W	BU95601/114116			SOLO	DUAL	SOLO	DUAL
Double Wasp	BU95631/114264	seriously					
R.280031	42-213/4822		46	60	12	173	150
	42-233/4842						

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
3rd
INJURY



PURPOSE OF FLIGHT:

Day training flight.

TECHNICAL OFFICER'S REPORT:

Nil

12/9/1957
100/100

NATURE OF ACCIDENT:

A/C AE925 taxied into a/c FD637,
while attempting to park a/c in
front of hangar.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other a/c.~~

9

9. Collision

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

ACTION TAKEN:

Log book endorsed.