

CASPIR Aircraft Accident Cards

Serial: 3655

Title: Fleet Fort serial:3655 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-December-11. Fleet Fort II s/n 3655. This accident involved 2 people. Longley RP, Ridley TH

Keywords: RCAF Fleet Fort II,3655,2 WSFS,2 Wireless School Flying Squadron,Didsbury Alberta,1943-December-11,Longley,RidleyRCAF L20

Created: 1943-12-11

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3655>

PURPOSE OF FLIGHT:

Wireless training exercise

TECHNICAL OFFICER'S REPORT:

Leaking oil tank

FE/ET/O/P/T

NATURE OF ACCIDENT:

High oil temp. & oil leaking in cockpit. Normal forced landing made. In taxiing to corner of field tail

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

wheel struck badger hole and was broken off.

FINDINGS:

SUMMARY No.

CLASSIFICATION:

33. Technical Defect

SECONDARY OR CONTRIBUTORY FACTORS:

NIL

ACTION TAKEN:

NIL.