

## CASPIR Aircraft Accident Cards

---

**Serial:** 11428

**Title:** Avro Anson Mk. II serial:11428 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1944-January-04. Anson II s/n 11428. This accident involved 2 people. Babey NB, Everett VH

**Keywords:** RCAFAnson II,11428,19 SFTS,19 Service Flying Training School,R1 Ensign,1944-January-04,Babey,EverrettRCAF L20

**Created:** 1944-01-04

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11428>



PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

Instruction on single engine procedure.

Nil

LUC/PCDUP/UCDL

NATURE OF ACCIDENT:

On demonstrating single engine landing pilot closed throttle of live engine on turning cross wind to do gliding approach. The horn cut-out was used and the throttles not opened again so the horn did not blow. Landing was made wheels up.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~34. Wheels up landing.~~

7  
*Others*

SECONDARY OR CONTRIBUTORY FACTORS:

~~2. Carelessness.~~

32  
*wc drill in air*

ACTION TAKEN:

Log book endorsed and instructor reprovod and logged.