

CASPIR Aircraft Accident Cards

Serial: FP910

Title: Avro Anson Mk. II serial:FP910 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-January-20. Anson II s/n FP910. This accident involved 2 people. Campbell FR, Maclennan DS

Keywords: RCAFAnson II,FP910,10 SFTS,10 Service Flying Training School,R2 Field,1944-January-20,Campbell,MaclennanRCAF L20

Created: 1944-01-20

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#FP910>

PURPOSE OF FLIGHT:

TECHNICAL OFFICER'S REPORT:

S.B.A. training.

Nil

NATURE OF ACCIDENT:

Pilot landed on field with poor surface, a/c swung to right, poor corrective measures taken and a/c nosed up after hitting soft spot and swinging to right.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~32. Pilot error.~~

2 Swung

SECONDARY OR CONTRIBUTORY FACTORS:

~~44. Bad surface.~~

~~36. Nosing up.~~

ACTION TAKEN:

Log Book Endorsed.