

CASPIR Aircraft Accident Cards

Serial: 11523

Title: Avro Anson Mk. II serial:11523 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-January-27. Anson II s/n 11523. This accident involved 1 person. Thomson A

Keywords: RCAFAnson II,11523,19 SFTS,19 Service Flying Training School,Aerodrome,1944-January-27,ThomsonRCAF L20

Created: 1944-01-27

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11523>

ACCIDENT CLASSIFICATION

UNIT	19 S.F.T.S Vulcan	COM.	4	PLACE	M.A.	DATE	27-1-44	TIME	2005
A/C TYPE	ANSON II	No.	11523	CRASH CAT.	"D"	H.Q. FILE	1100-115-23		
PERSONNEL		RANK	NUMBER	DUTY	INJURIES	S.E.	M.E.	DAY	NIGHT
THOMSON, A.		LAC	R215039	PP	Uninj.		x		x
						SIGNAL			
						NO.	DATE		
						A.91	27-1		
						D 14 (REVISED)			
						NO.	CHECKED		
						3			
						#39			
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS					
Jacobs L6MB		16214/2396 Nil		INST.	NIGHT	ON TYPE		TOTAL	
		17655/9034 Nil				SOLO	DUAL	SOLO	DUAL
				17	9	13	34	41	66

COMMAND

MONTH

STAGE OF FLIGHT

- 7
- 4
- 2
- 1
- 7
- 4
- 2
- 1
- FORCED LANDING
- TAXIING
- LANDING
- TAKE-OFF
- FLIGHT
- START BY
- FATAL
- INJ
- INJURY
- 3RD
- 5
- 4

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Night circuits and landing.

NATURE OF ACCIDENT:

Wheels up landing at night.

TECHNICAL OFFICER'S REPORT:

LUC/PEDUF/UCDL

Nil

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~34. Wheels up landing.~~

7. Others

(7)

SECONDARY OR CONTRIBUTORY FACTORS:

~~32. Pilot error.~~

32. w/c drill - in air

(32)

ACTION TAKEN:

Log book endorsed and charged with negligence.