

CASPIR Aircraft Accident Cards

Serial: 8295

Title: Avro Anson Mk. II serial:8295 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-January-31. Anson II s/n 8295. This accident involved 1 person. Naylor JY

Keywords: RCAFAnson II,8295,5 SFTS,5 Service Flying Training School,Aerodrome,1944-January-31,NaylorRCAF L20

Created: 1944-01-31

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8295>

ACCIDENT CLASSIFICATION

UNIT	5 S.F.T.S. Brantford		COM.	1	PLACE	M.A.		DATE	31-1-44	TIME	0355	
	A/C TYPE	ANSON II		NO.	8295	CRASH CAT.	"A"	H.Q. FILE	1100-82-95			
		S.E.	M.E.	DAY	NIGHT							
			X		X							
PERSONNEL			RANK	NUMBER	DUTY	INJURIES		SIGNAL				
NAYLOR, J.Y.			LAC	R204525	PP	Uninj.		NO.	DATE			
								A.9	31-1			
								D 14 (REVISED)				
								NO.	CHECKED			
								2	<input checked="" type="checkbox"/>			
								#45				
ENGINE		ENGINE NUMBER (S)			HOURS FLOWN BY PILOTS							
Jacobs L6MB		26103/19991	Nil		INST.	NIGHT	ON TYPE		TOTAL			
		26104/19992	"				SOLO	DUAL	SOLO	DUAL		
					17	10	17	37	45	74		

COMMAND
MONTH
STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAKING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ
3rd
INJURY
5
4

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Night circuits, Seq. 26.

NATURE OF ACCIDENT:

A/C ground looped on landing.

TECHNICAL OFFICER'S REPORT:

Nil

L.S./100

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~38. Ground loop.~~

(2)

2. Sweung

SECONDARY OR CONTRIBUTORY FACTORS:

~~44. Bad surface.~~

ACTION TAKEN:

Nil