

ACCIDENT CLASSIFICATION

UNIT 9 B.G.S.. Mont Joli	COM. 3	PLACE M.A.		DATE 15-2-44		TIME 1345	
				H.Q. FILE 1100-74-34			
A/C TYPE BATTLE III		No. 7434		CRASH CAT. "D"1	S.E. x	M.E. x	NIGHT x
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL
EDMUNDS, R.R.		P/O	J26125	P	Uninj.		No. DATE
BURBURY, G.D. NZ		LAC	427951	AG	Uninj.		N.73 15-2
DERBYSHIRE, J.		LAC	R264171	AG	Uninj.		D 14 (REVISED)
							No. CHECKED
							1
							#2
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS			
Merlin III		456/5605 slight.		INST.	NIGHT	ON TYPE	
						TOTAL	
				30	15	SOLO DUAL	SOLO DUAL
						289 1	250 127

ACCIDENT CLASSIFICATION

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXIING
LANDING
TAKEOFF
FLIGHT
STATRY
FATAL
INJ.
3RD
INJURY

RAF M2

PURPOSE OF FLIGHT:

Scheduled gunnery exercise.

TECHNICAL OFFICER'S REPORT:

rudder

NATURE OF ACCIDENT:

After landing a/c was taxiing in an easterly direction on runway when stbd tire blew out. This caused a/c to swing off runway into deep snow.

NIL

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~43. Tire trouble.~~

2. Landing

(2)

SECONDARY OR CONTRIBUTORY FACTORS:

~~61. Swinging on landing.~~

~~44. Bad surface.~~

~~36. Nosing up.~~

37. Tire Burst

(37)

ACTION TAKEN:

NIL