

		ACCIDENT CLASSIFICATION																														
TYPE OF A/C	UNIT	9 B.G.S. MOUNT JOLI										COM.	3		PLACE	1 mile S.W. of Baie Des Sables										DATE	23-1-44		TIME	1120		COMMAND
	A/C TYPE	BATTLE										NO.	5332		CRASH CAT.	4014 B		S.E.	X		M.E.			DAY	X		NIGHT	1100-53-32				
	PERSONNEL											RANK			NUMBER			DUTY			INJURIES			SIGNAL								
	JONES, E.											F/O			J9280			P			Uninj.			NO.			DATE					
TYPE OF UNIT	CHADWICK, A.J.M.											S/L			70122			AG			Uninj.			N.74			23-1					
																								D 14 (REVISED)								
																								NO.			CHECKED					
																								2			#7					
CATEGORY	ENGINE											ENGINE NUMBER (S)	8512/1971 slight										HOURS FLOWN BY PILOTS								STAGE OF FLIGHT	
	MERLIN II														INST.			NIGHT			ON TYPE		TOTAL									
															36			17			SOLO	DUAL		SOLO	DUAL							
		ACCIDENT CLASSIFICATION																														

PURPOSE OF FLIGHT:

Scheduled gunnery exercise.

NATURE OF ACCIDENT:

Engine failure in the air, probable internal glycol leak, large amount of white smoke coming out from both exhaust stacks.

TECHNICAL OFFICER'S REPORT:

Internal glycol leak "A" bank.

1-2/10/11 4/10/11

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~54. Engine failure in the air.~~

17. Forced Landing

(17)

SECONDARY OR CONTRIBUTORY FACTORS:

~~33. Technical defect.~~

No. engine trouble - accident

(26)

ACTION TAKEN:

Nil