



PURPOSE OF FLIGHT:

Taxiing on main aerodrome.

NATURE OF ACCIDENT:

Crane FJ215 pulled out of line on main tarmac and right wing tip struck left wing tip of Crane 7820 which was stopped with engines running on Main Tarmac.

TECHNICAL OFFICER'S REPORT:

*M. J. ...*

*7820/11*

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other A/c~~

*9. Collision*

9

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness~~

ACTION TAKEN:

Logged; Log Book Endorsed; 7 days C.B.; 14 days R.P. and grounded for 1 month.