

CASPIR Aircraft Accident Cards

Serial: 2982

Title: North American Harvard Mk.II serial:2982 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-January-04. Harvard II s/n 2982. This accident involved 2 people. Cotton KG, Franken AP

Keywords: RAFHarvard II,2982,34 SFTS,34 Service Flying Training School,Aerodrome,1944-January-04,Cotton,FrankenRCAF L20

Created: 1944-01-04

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2982>

PURPOSE OF FLIGHT:

Local exercises.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Rudder found to be damaged after flight.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

Remarks of Unit C.O.

On landing, pilot was informed base of the rudder was damaged presumably earlier in the day as no instance occurred during the flight where that could have been caused.

CLASSIFICATION:

57. Miscellaneous.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil