

CASPIR Aircraft Accident Cards

Serial: FE912

Title: North American Harvard Mk. IIB serial:FE912 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-January-18. Harvard IIB s/n FE912. This accident involved 2 people. Evans RC, Smith WR

Keywords: RAFHarvard IIB,FE912,34 SFTS,34 Service Flying Training School,Aerodrome,1944-January-18,Evans,SmithRCAF L20

Created: 1944-01-18

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE912>

ACCIDENT CLASSIFICATION

UNIT 34 S.F.T.S. Medicine Hat	COM. 4	PLACE M.A.	DATE 18-1-44		TIME 1445		
			H.Q. FILE 1300-FE912				
A/C TYPE HARVARD IIB	No. FE912	CRASH CAT. "E"1/72	S.E. x	M.E.	DAY x	NIGHT	
			PERSONNEL				
SMITH, W.R.	RANK F/O	NUMBER 152258	DUTY FI	INJURIES Uninj.		SIGNAL No. DATE	
EVANS, R.C.	RANK LAC	NUMBER 1583548	DUTY PP	INJURIES Uninj.		D 14 (REVISED) No. CHECKED	
ENGINE Wasp R.1340/ANI		ENGINE NUMBER (S) 42-761/15897 Nil	HOURS FLOWN BY PILOTS				
			ON TYPE		TOTAL		
		INST.	NIGHT	SOLO	DUAL	SOLO	DUAL
		-	-	460	80	500	145
				29	46	63	94

ACCIDENT CLASSIFICATION

COMMAND
MONTH
STAGE OF FLIGHT

4
2
1
7
4
2
1
FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAIRY
FATAL
INJ
INJURY
3RD
5
RAF
W

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

A B C D

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62

PURPOSE OF FLIGHT:

Elementary formation flying.

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 943.15 hours.

NATURE OF ACCIDENT:

On taxiing off runway, after landing,
the tail wheel tire burst.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

TC-121

CLASSIFICATION:

43. Tire trouble.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil