

CASPIR Aircraft Accident Cards

Serial: FE915

Title: North American Harvard Mk. IIB serial:FE915 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1944-January-20. Harvard IIB s/n FE915. This accident involved 1 person. Maynard CWH

Keywords: RAFHarvard IIB,FE915,34 SFTS,34 Service Flying Training School,Aerodrome,1944-January-20,MaynardRCAF L20

Created: 1944-01-20

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE915>

PURPOSE OF FLIGHT:

Cross country solo.

NATURE OF ACCIDENT:

Tail wheel tire burst on landing.

TECHNICAL OFFICER'S REPORT:

Tail wheel tire burst after life of 276.10 hours.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

15. Tire failure.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil