

CASPIR Aircraft Accident Cards

Serial: AJ932

Title: North American Harvard Mk. II serial:AJ932 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1944-January-26. They are: Harvard II s/n 2645, Harvard II s/n AJ932. This accident involved 2 people. McMullin WK, Togwell RGW

Keywords: RAFHarvard II,AJ932,34 SFTS,34 Service Flying Training School,Aerodrome,1944-January-26,McMullin,TogwellRCAF L20

Created: 1944-01-26

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ932>

ACCIDENT CLASSIFICATION

UNIT	34 S.F.T.S. Medicine Hat		COM.	4	PLACE	M.A.		DATE	26-1-44	TIME	2030	
	A/C TYPE		HARVARD II HARVARD II		NO.	2645 D AJ932		CRASH CAT	Nil "E" ¹		H.Q. FILE	1100-26-45
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL					
McMULLIN, W.K.		LAC	R176580	PP	Uninj.		NO.	DATE				
TOGWELL, R.C.W.		F/O	51062	PP	Uninj.		D 14 (REVISED)					
							NO.	CHECKED				
							#92					
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS								
Wasp S3HI		213608/10982 Nil 213817-11546 nil		INST.	NIGHT	ON TYPE		TOTAL				
						SOLO	DUAL	SOLO	DUAL			
				18	21	22	55	57	91			
				35	23	53	100	83	162			

COMMAND
MONTH
STAGE OF FLIGHT

7
4
2
1
7
4
2
1
FORCED LANDING
TAXIING
LANDING
TAKE-OFF
FLIGHT
STARTRY
FATAL
INJ.
3rd
5
M Z

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Solo night flying practice.
Solo night flying cross - country.

TECHNICAL OFFICER'S REPORT:

Nil

NATURE OF ACCIDENT:

Pupil was doing vital actions in
a/c Harvard 2645 with engine running,
when a/c moved forward and the wing
tip struck the rudder of AJ932 which
a/c was stopped at the taxi post
signalling for permission to take-off.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

70 A 100 T
1972

CLASSIFICATION:

3. Hitting other a/c.

SECONDARY OR CONTRIBUTORY FACTORS:

24. Carelessness.

ACTION TAKEN:

Log book endorsed "Gross Carelessness" and awarded
7 days C.C.