

61 () 60 () 59 () 58 () 57 () 56 () 55 () 54 () 53 () 52 () 51 () 50 () 49 () 48 () 47 () 46 () 45 () 44 () 43 () 42 () 41 () 40 () 39 () 38 () 37 () 36 () 35 () 34 () 33 () 32 () 31 () 7 ()

ACCIDENT CLASSIFICATION

UNIT 1 O.T.U. BAGOTVILLE		COM. E	PLACE M.A.		DATE 15-1-44	TIME 1910		
A/C TYPE HURRICANE XII HURRICANE XIIA		NO. 5455 BW835 D	CRASH CAT. "B" "C"		S.E. X	M.E. DAY	NIGHT X	
PERSONNEL		RANK	NUMBER	DUTY	INJURIES		SIGNAL	
ODEN, O.H.		NZ F/O	417095	P	UNINJ.		NO. DATE	
ALLEN, P.J.		GB SGT	1601497	P	Uninj.		A.214 15-1	
							D 14 (REVISED)	
							NO. CHECKED	
							6	
							#9	
ENGINE		ENGINE NUMBER (S)		HOURS FLOWN BY PILOTS				
Packard Merlin		/A503 slightly /A285 Nil		INST.	NIGHT	ON TYPE		TOTAL
						SOLO	DUAL	SOLO DUAL
				59	55	40	-	651 154
				37	10	15	-	145 143

COMMAND
MONTH
STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ.
INJ. 3RD
INJ. 5

TYPE OF A/C
TYPE OF UNIT
CATEGORY

ACCIDENT CLASSIFICATION

1 () 2 () 3 () 4 () 5 () 6 () 7 () 8 () 9 () 10 () 11 () 12 () 13 () 14 () 15 () 16 () 17 () 18 () 19 () 20 () 21 () 22 () 23 () 24 () 25 () 26 () 27 () 28 () 29 () 30 () RAF M N

PURPOSE OF FLIGHT:

Low flying.

TECHNICAL OFFICER'S REPORT: *MULT*

Nil

*TCR/ACT
TCR/ACT/XA*

NATURE OF ACCIDENT:

Hurricane 5455 proceeding on taxi-strip prior to take off collided with parked Hurricane BW835 which had failed to take-off due to engine trouble and had re-entered taxi strip and was not seen by pilot of Hurricane 5455.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

~~3. Hitting other a/c.~~
9. Collision

9

SECONDARY OR CONTRIBUTORY FACTORS:

~~24. Carelessness.~~

ACTION TAKEN:

1000 lines each. Each logged. Log books endorsed F/O Oden 4 days leave cancelled off graduating leave. SGT Allen two weeks extra ground-duties.