

## CASPIR Aircraft Accident Cards

---

**Serial:** EB603

**Title:** Airspeed Oxford Mk. V serial:EB603 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1944-January-20. Oxford V s/n EB603. This accident involved 1 person. Hamilton JE

**Keywords:** RAFOxford V,EB603,35 SFTS,35 Service Flying Training School,Aerodrome,1944-January-20,HamiltonRCAF L20

**Created:** 1944-01-20

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#EB603>



PURPOSE OF FLIGHT:

Flying Training.

NATURE OF ACCIDENT:

Whilst a/c was being started, port engine back fired and caught fire in the carb. intake and in rear of engine. There was heavy wind at the time but with aid of fire extinguisher and tender, flames were controlled and put out.

CLASSIFICATION:

57. Miscellaneous.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

Backfire in carburettor intake.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

ACTION TAKEN:

Nil.